

Архангельск (8182)63-90-72  
 Астана (7172)727-132  
 Астрахань (8512)99-46-04  
 Барнаул (3852)73-04-60  
 Белгород (4722)40-23-64  
 Брянск (4832)59-03-52  
 Владивосток (423)249-28-31  
 Волгоград (844)278-03-48  
 Вологда (8172)26-41-59  
 Воронеж (473)204-51-73  
 Екатеринбург (343)384-55-89  
 Иваново (4932)77-34-06

Ижевск (3412)26-03-58  
 Иркутск (395)279-98-46  
 Казань (843)206-01-48  
 Калининград (4012)72-03-81  
 Калуга (4842)92-23-67  
 Кемерово (3842)65-04-62  
 Киров (8332)68-02-04  
 Краснодар (861)203-40-90  
 Красноярск (391)204-63-61  
 Курск (4712)77-13-04  
 Липецк (4742)52-20-81

Магнитогорск (3519)55-03-13  
 Москва (495)268-04-70  
 Мурманск (8152)59-64-93  
 Набережные Челны (8552)20-53-41  
 Нижний Новгород (831)429-08-12  
 Новокузнецк (3843)20-46-81  
 Новосибирск (383)227-86-73  
 Омск (3812)21-46-40  
 Орел (4862)44-53-42  
 Оренбург (3532)37-68-04  
 Пенза (8412)22-31-16

Пермь (342)205-81-47  
 Ростов-на-Дону (863)308-18-15  
 Рязань (4912)46-61-64  
 Самара (846)206-03-16  
 Санкт-Петербург (812)309-46-40  
 Саратов (845)249-38-78  
 Севастополь (8692)22-31-93  
 Симферополь (3652)67-13-56  
 Смоленск (4812)29-41-54  
 Сочи (862)225-72-31  
 Ставрополь (8652)20-65-13

Сургут (3462)77-98-35  
 Тверь (4822)63-31-35  
 Томск (3822)98-41-53  
 Тула (4872)74-02-29  
 Тюмень (3452)66-21-18  
 Ульяновск (8422)24-23-59  
 Уфа (347)229-48-12  
 Хабаровск (4212)92-98-04  
 Челябинск (351)202-03-61  
 Череповец (8202)49-02-64  
 Ярославль (4852)69-52-93

Киргизия (996)312-96-26-47

Россия (495)268-04-70

Казахстан (772)734-952-31

<https://leitenberger.nt-rt.ru/> || [bge@nt-rt.ru](mailto:bge@nt-rt.ru)

## TEMPERATURE TRANSMITTER



Transmitter (TT 01)

### DESCRIPTION

Temperature transmitter - the 2 in 1 solution -  
 2 analogue outputs in 1 device

Temperature and humidity high quality transmitter for your demand of accuracy and long time stability combined with process technology. We offer you monitoring solutions specially for the gathering and visualization of measuring sizes. Measurement, display and output of values.

- digital RS485 ModBUS RTU connection
- high accuracy
- easy wall-mounting
- high grade of individualization (see table)
- high quality display
- lighting with automatic brightness control

### TABLE

Transmitter	Temperature	Humidity	Temperature/Humidity
Measurement range and accuracy	-30 °C...+50 °C, 1/3 B	0...99 % RH, 2 % 20...85 % RH, 4 %	-30 °C...+50 °C, 1/3 B 0...99 % RH, 2 % -30 °C...+50 °C, 1/3 B 20...85 % RH, 4 %
LCD	with or without	with or without	with or without
Analogue output options	4...20 mA 4...20 mA AND 0...10 V 0...10 V	4...20 mA 4...20 mA AND 0...10 V 0...10 V	4...20 mA 4...20 mA AND 0...10 V 0...10 V