

Архангельск (8182)63-90-72
Астана (7172)727-132
Астрахань (8512)99-46-04
Барнаул (3852)73-04-60
Белгород (4722)40-23-64
Брянск (4832)59-03-52
Владивосток (423)249-28-31
Волгоград (844)278-03-48
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-89
Иваново (4932)77-34-06

Ижевск (3412)26-03-58
Иркутск (395)279-98-46
Казань (843)206-01-48
Калининград (4012)72-03-81
Калуга (4842)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Липецк (4742)52-20-81

Магнитогорск (3519)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-64-93
Набережные Челны (8552)20-53-41
Нижний Новгород (831)429-08-12
Новокузнецк (3843)20-46-81
Новосибирск (383)227-86-73
Омск (3812)21-46-40
Орел (4862)44-53-42
Оренбург (3532)37-68-04
Пенза (8412)22-31-16

Пермь (342)205-81-47
Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-64
Самара (846)206-03-16
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78
Севастополь (8692)22-31-93
Симферополь (3652)67-13-56
Смоленск (4812)29-41-54
Сочи (862)225-72-31
Ставрополь (8652)20-65-13

Сургут (3462)77-98-35
Тверь (4822)63-31-35
Томск (3822)98-41-53
Тула (4872)74-02-29
Тюмень (3452)66-21-18
Ульяновск (8422)24-23-59
Уфа (347)229-48-12
Хабаровск (4212)92-98-04
Челябинск (351)202-03-61
Череповец (8202)49-02-64
Ярославль (4852)69-52-93

Киргизия (996)312-96-26-47

Россия (495)268-04-70

Казахстан (772)734-952-31

<https://leitenberger.nt-rt.ru/> || bge@nt-rt.ru

DIGITAL HAND TACHOMETER FOR REVOLUTION MEASURES EFFECTED WITHOUT CONTACT



item number :
MT 6000 (041001)

DESCRIPTION

- The multifunctional digital hand tachometer is a robust high-quality tester for revolution measures effected without contact as well as for contact-measures of revolutions and speed.
- Extensive range and automatic memory of results.
 - range of 0.5...100 000 RPM and up to 2000 m/min
 - 5-digit LC display, 7-segments digits 10.2 mm high
 - accuracy $\pm 0.05\%$, ± 1 digit of the measurement
 - power supply by 4 ps. Mignon R6 1.5 V
- Ranges contact measure: • ...19999 RPM, • 0.05...1999.9 m/min, • 0.2...6560 feet/min
- Contactless measure: • 5...99999 RPM
- **SCOPE OF DELIVERY**
- 1 detector
- 1 ring gear wheel and 0.60 m (24 in.) reflecting tape
- 1 rubber contact piece
- 1 storage bag with foam material inlet

SPARE PARTS

- ET 43 (120410) reflection tape 60 cm (1,97 ft)
- ET 434 (121468) female rubber contact piece
- ET 435 (121469) male rubber contact piece
- ET 436 (121470) combined surface speed disc meter/feet
- ET 437 (121471) rotating ring